

### Lager

5200 0042	Nadellager HK 12-12
5200 0041	Nadellager HK 12-14
5200 0040	Nadellager HK 15-16
5200 0044	Kugellager 6001
5200 0045	Kugellager 6001/2 RS
5200 0046	Kugellager 6002
5200 0047	Kugellager 6002/2 RS



### U-Scheiben

#### verzinkt

5200 0086	20/13 Ø x 2,0 mm
5200 0087	24/13 Ø x 1,0 mm
5200 0088	24/13 Ø x 2,0 mm
5200 0089	24/13 Ø x 2,5 mm
5200 0090	20/14 Ø x 0,5 mm
5200 0093	22/16 Ø x 1,0 mm
5200 0092	26/16 Ø x 0,5 mm
5200 0091	26/16 Ø x 1,0 mm
5200 0060	Selbstsichernde Mutter M 12, verzinkt, DIN 985

#### Kunststoff

9200 0095	26/16,5 Ø x 1,0 mm
-----------	--------------------

#### VA

5300 3914	Selbstsichernde Mutter M 12, VA, DIN 985
9200 0615	22/16 Ø x 0,5 mm
9200 0616	22/16 Ø x 1,0 mm

#### Schmiernippel

5200 0080	Trichter-Schmiernippel D1A 6 mm Ø, DIN 3405
-----------	---



### Bearings

5200 0042	needle bearings HK 12-12
5200 0041	needle bearings HK 12-14
5200 0040	needle bearings HK 15-16
5200 0044	ball bearings 6001
5200 0045	ball bearings 6001/2 RS
5200 0046	ball bearings 6002
5200 0047	ball bearings 6002/2 RS

### Washers

#### galvanized

5200 0086	20/13 Ø x 2,0 mm
5200 0087	24/13 Ø x 1,0 mm
5200 0088	24/13 Ø x 2,0 mm
5200 0089	24/13 Ø x 2,5 mm
5200 0090	20/14 Ø x 0,5 mm
5200 0093	22/16 Ø x 1,0 mm
5200 0092	26/16 Ø x 0,5 mm
5200 0091	26/16 Ø x 1,0 mm
5200 0060	Self-locking nut M 12, galvanized, DIN 985

#### Kunststoff

9200 0095	26/16,5 Ø x 1,0 mm
-----------	--------------------

#### Stainless steel

5300 3914	Self-locking nut M 12, galvanized, DIN 985
9200 0615	22/16 Ø x 0,5 mm
9200 0616	22/16 Ø x 1,0 mm

#### Grease nipple

5200 0080	Funnel-type lubricating nipple D1A 6 mm Ø, DIN 3405
-----------	---